

Linea Research System Engineer v1.0.0.0 - Release Notes

Release Date: 15/10/2024

New Features

- ID: 3238 - Snapshot Store/Recall
- ID: 3283 - Allow OEMs to edit locked device presets from the OEM library
- ID: 3293 - Re style Left hand tool bar to maximize space in the detail and explorer views
- ID: 3316 - Allow the user to view and edit the Dante name
- ID: 3936 - Add ability to have multiple OEM IDs in one OEM account
- ID: 3980 - Add expand and collapse buttons for the group detail flyout
- ID: 4021 - Improve the look of module selection summary
- ID: 4023 - Add load confirmation to modules after successfully loading a preset
- ID: 4024 - Add tool tips to un-selectable files and folders in the library
- ID: 4026 - Change 'pin to change' button on device memory folder
- ID: 4066 - Align top of repository device memory with device memory pane
- ID: 4093 - Remove error that says to load device memory again via SE 7
- ID: 4112 - Add new OEM accounts and device models
- ID: 4115 - Add application quit dialogue
- ID: 4136 - Change Text 'Flatten' to 'Bypass' in the EQ Views
- ID: 4138 - Add device memory selection button on the device in presets view

- ID: 4140 - Add some text to prompt the user to load or save a preset
- ID: 4141 - Add Text to prompt user when a preset is selected
- ID: 4142 - Add text for user when device memory is selected
- ID: 4143 - Add some text to prompt the user on how to edit device memory folders
- ID: 4150 - Preset preview tool bar visible when preset load summary is in view

Improvements

- ID: 3886 - Double click gain slider control should reset value to zero
- ID: 3887 - Add preset folder drag validation
- ID: 3912 - User should not be able to drag a drive module past the edge of the viewable area
- ID: 3913 - User should not be able to drag the canvas so that the edges of the canvas move within the viewable area
- ID: 3914 - On Load, all drive modules should snap to the closest grid anchor point
- ID: 3915 - When dragging a drive module around, it should be snapping to the closest grid anchor points
- ID: 3986 - Add sort option to the Group mixer
- ID: 4028 - Device name does not update in the preset save summary
- ID: 4029 - Converting folder to device memory will convert it to the old style
- ID: 4033 - Exception dragging presets

Bug Fixes

- ID: 3259 - Overlay Flush Not working
- ID: 3308 - Exception when loading 8 X 88C at Virtuals in Dev Mode
- ID: 3315 - Exception on Start up / Virtuals

- ID: 3482 - Delay defaults to 0.01ms
- ID: 3521 - Errors and exceptions - Log file
- ID: 3642 - Exception when navigating from Logs to EQ window
- ID: 3645 - Random Exception navigating around app
- ID: 3781 - Input FIR OEM flatten
- ID: 3792 - Open File Overwrites Device memory when apply settings only is selected
- ID: 3798 - DOT Audio incorrect virtual devices
- ID: 3804 - Exception removing virtual device
- ID: 3809 - Exception when applying a preset
- ID: 3818 - Persist navigation selection in the preset library
- ID: 3824 - Multi-Select / Tune View / EQ Graph Flickering when dialing in new value
- ID: 3856 - Bug with bridging a multi-selected device
- ID: 3884 - Group can get stuck on busy
- ID: 3885 - Group bar can sometimes be added outside of canvas extent
- ID: 3888 - Devices will sometimes not appear in the explorer view in the setup workflow
- ID: 3894 - Apply file only operation
- ID: 3902 - Setup detail view shows no device selected when one should be
- ID: 3906 - Unable to lock device memory presets in OEM mode
- ID: 3925 - Group page not releasing with multi-select
- ID: 3927 - Address unreliable preset drag-and-drop behavior
- ID: 3928 - Improve dragging presets to device memory
- ID: 3929 - Enable drag-and-drop for rearranging presets in amp memory
- ID: 3930 - Update 'Convert Selected Folder to Device Memory' function
- ID: 3931 - Prevent duplicate location numbers in device memory
- ID: 3932 - Implement notification for 2-way presets in 1-way locations

- ID: 3933 - Enhance handling of presets from multiple folders
- ID: 3938 - Drag area on group bar in tune explorer
- ID: 3939 - Inputs/Outputs don't highlight on hover
- ID: 3940 - No input to delay from drive module
- ID: 3941 - Textbox with no text is too narrow to click on easily
- ID: 3942 - Show text box outline on hover
- ID: 3943 - DSP labels need to be the same color as the device name
- ID: 3944 - Group color text should adapt to the color
- ID: 3948 - Exception when repeatedly pressing multi-select mode button
- ID: 3949 - Drive modules sometimes load outside the canvas
- ID: 3975 - Text color on drive modules is different across device models when group is armed
- ID: 3976 - Clicking in textbox to rename input or output on module should not select the module
- ID: 3977 - Input or output should deselect when a group is selected