
Overview:

In this release, we have made improvements to ensure the reliability and performance of M and C series devices. These changes are vital to maintaining the highest quality and safety standards for our users.

We encourage all users to update to this latest firmware version to ensure your devices function optimally. Please follow the instructions in the "How to Update" section below to update.

Features:

- We have added an audio detect feature to the fall-over options. You can now choose to detect the Dante stream or original audio for fall-over.
- Added fall-back options to fall-over - It is now possible to set how fast you fall-back to an input source after fall-over.

Enhancements:

- Improved network stability with the new Linea Research Q-Sys plug-in "Linea Research Amplifier Control V3".

Note: **DO NOT USE** Q-Sys plug-in "Linea Research Amp Control V2" with firmware V1.680.

Bug Fixes:

- Fixed high-temperature warning when a device's low-temperature warning was triggered.

How to Update:

Please use System Engineer 7 v7.03.04 or later or Se8 Beta 0.3.17.0 or later to update your device firmware.

Support and Feedback:

<https://enquiries.linea-research.co.uk/>